

# Electric parts checking mod. 2T 80-85-125-144-250-300 temperature 20°c



# Spark plug check

Correct electric resistance 5.0 K. $\Omega$  +/- 3%



## Secondary coil check

Tip on ground frame/coil & tip on spark plug wire

Correct electric resistance 6.2 K. $\Omega$  +/- 3%





# Primary coil check

Tip on ground frame/coil & tip on positive coil

Correct electric resistance 0.5  $\Omega$  +/- 25%



## Stator winding check

Tip on red/white cable & tip on red/black cable

Correct electric resistance **26.0**  $\Omega$  +/- **20%** 





## Pick-up check

Tip on red calbe & tip on green/cable

Correct electric resistance 100 'Ω +/- 20%